

#### Moxa Inc.

13F, No. 3, Sec. 4, New Taipei Blvd., Xinzhuang Dist. New Taipei City 242032, Taiwan, R.O.C.

Tel: +886-2-8919-1230 Fax: +886-2-8522-8623 www.moxa.com

## Product Change Notification—PCN# PCN000 001105

May 05, 2025

Dear Valued Customer,

We would like to inform you that Moxa is going to make changes to the AIG-301 Series. These changes will be implemented by May 05, 2025. Please review the details below to determine how these changes will affect your products and/or operations.

## What will change?

## **Software**

#### **New Features**

1. Adds the Telit LE910C4-WWXD module support for AIG-301-T-AP-AZU-LX/ AIG-301-AP-AZU-LX

#### Fixed Issues

- 1. An instance of the DO value set by Modbus did not update correctly.
- 2. An unresponsive refresh button on the I/O page.
- 3. An error message "Sparkplug service is busy (please try again later)" appeared when configuring Sparkplug.
- 4. Selection of the "Only send changed values" option for Publish Immediately mode in Sparkplug did not save.

## **Known Issues**

1. The Sparkplug configuration will be lost if power is cycled within 10 seconds after saving the configuration. Note: Sparkplug configuration will take at least one minute when many messages or tags are selected. Wait at least one minute after saving the configuration.

#### **Enhancements**

- 1. The DLM Client for the Moxa DLM Service now implements a backoff mechanism to prevent excessive message repetition during high-frequency events, optimizing events reported while ensuring critical notifications remain visible.
  - If the same event occurs five times within a 5-minute window, the system enters backoff mode, progressively increasing the message delay up to a maximum of 60 minutes.
  - During backoff, events are sent as compressed messages with an indication of suppression count (e.g., "backed off for x times").
  - Normal message delivery is resumed once the event stops occurring or after a device

Form number: HQ-PD.232 Version: 1.8 Page 1/2



#### Moxa Inc.

13F, No. 3, Sec. 4, New Taipei Blvd., Xinzhuang Dist. New Taipei City 242032, Taiwan, R.O.C.

Tel: +886-2-8919-1230 Fax: +886-2-8522-8623 www.moxa.com

reboot.

#### **Notes**

1. The upgrade process from firmware v1.6 to v1.7 will require approximately 20 minutes.

## **Hardware**

- 1. The cellular module of the AIG-301-AP-AZU-LX/ AIG-301-T-AP-AZU-LX will be changed from the Telit LE910C4-AP to the Telit LE910C4-WWXD.
- 2. The AIG-301-AP-AZU-LX doesn't support the Regulatory Compliance Mark (RCM) certification.

# Which products will be affected?

Product Name	<b>Current Version</b>	New Version
AIG-301 Series	V1.6.0	V1.7.0

## When will the new versions be available?

Product Name	New Version	Available for Order
AIG-301 Series	V1.7.0	Available Now

If you have any questions, please contact <u>alfredfh.li@moxa.com</u>, or contact your regional sales representative.

Form number: HQ-PD.232 Version: 1.8 Page 2/2