

Moxa Inc.

13F, No. 3, Sec. 4, New Taipei Blvd., Xinzhuang Dist. New Taipei City 242032, Taiwan, R.O.C.

Tel: +886-2-8919-1230 Fax: +886-2-8522-8623 www.moxa.com

Product Change Notification—PCN# PCN001160

October 27, 2025

Dear Valued Customer.

We would like to inform you that Moxa will release **Moxa Industrial Linux (MIL) v3.4.1** for the UC Series computers on **October 28, 2025**.

In MIL 3.4.0 released in last month, it introduced new commands in the **Moxa Computer Interface Manager (MCIM)** utility to make it easier to customize digital input (DI) and push-button (RESET or FN button) event scripts. However, we discovered that the legacy configuration methods supported in MIL 3.0 to 3.3—such as setting the push-button to restore a snapshot or trigger a user-defined script—were unintentionally not backward compatible in MIL 3.4.0.

We sincerely apologize for any inconvenience this may have caused. To correct this issue, we are releasing **MIL 3.4.1**, which restores backward compatibility along with other improvements. If you have provisioning scripts that rely on **mx-interface-mgmt dio** or **mx-interface-mgmt button** created under MIL 3.0–3.3, please ensure that you use MIL 3.4.1 instead of MIL 3.4.0.

Please review the details below to determine how these changes will affect your products and/or operations.

What will change in Moxa Industrial Linux 3.4.1?

New Features

- Moxa Connection Manager (MCM) v1.7.14
 - o Support for configuring DHCP lease time and IP range in Wi-Fi Soft-AP mode
 - Added encryption mode options for Wi-Fi Soft-AP (OPEN and WPA2) in addition to WPA1+WPA2
 - The DHCP server now supports the DNS configuration option
 - Cellular diagnostic function now supports the UC-4400A with a 5G modem

Enhancements

- Moxa Connection Manager (MCM) v1.7.14
 - Improve SIM card switching time for Telit 4G modules
 - Add an option to allow non-MCM managed Ethernet interfaces to be controlled by the networking service
 - Allow an empty IP gateway value to be set

Form number: HQ-PD.232 Version: 1.8 Page 1/3



Moxa Inc.

13F, No. 3, Sec. 4, New Taipei Blvd., Xinzhuang Dist. New Taipei City 242032, Taiwan, R.O.C.

Tel: +886-2-8919-1230 Fax: +886-2-8522-8623

- Added support to enable the DHCP server on multiple LAN interfaces simultaneously (previously limited to one)
- Improved invalid Wi-Fi SSID and password detection in the MCM GUI; users are now blocked from saving configurations with invalid characters
- Allowed the & character in Wi-Fi passwords

Bugs fixed:

- Moxa Computer Interface Manager (MCIM):
 - Fixed an issue where the legacy method for configuring push-button actions (supported in MIL 3.0–3.3) was not available in MIL 3.4.0; support has been restored in MIL 3.4.1
 - Fixed an issue where the legacy method for configuring Digital Input (DI) event scripts (supported in MIL 3.0–3.3) was not supported in MIL 3.4.0; support is now restored in MIL 3.4.1
 - [UC-1200A/UC-2200A only] Updated mount state handling logic to fix an issue where unexpected filesystem mounts could cause the SD/USB LED to turn off unexpectedly
- Moxa Connection Manager (MCM) v1.7.14:
 - Fixed an issue where configuring the out-of- the -box UC cellular connection with a SIM card that has a PIN lock would fail to connect to the Internet until the system was rebooted
 - Fixed unstable reconnections when connecting to Wi-Fi BSSIDs under the same SSID
 - Fixed an issue where an unresponsive GPSD service caused MCM to stop working during GPS port sync by adding a timeout
 - Fixed an issue where MCM v1.2/v1.3 configuration files became incompatible when upgrading to v1.7.5 (MIL 3.4.0) via v1.4 or v1.5. The issue did not occur when upgrading directly from v1.2/v1.3 to v1.7.5 or v1.4/v1.5 to v1.7.5
- Moxa Software Updater (MSU):
 - Fix an issue where using the command mx-sw-updater upgrade --local to upgrade the system via the offline method may still require Internet access for dependency download.
- Moxa Power Manager (MPM):
 - [UC-3400A only] Fixed an issue where the Wi-Fi interface could become unresponsive or fail to reconnect after recovering from MPM power conservation mode

Form number: HQ-PD.232 Version: 1.8 Page 2/3



Moxa Inc.

13F, No. 3, Sec. 4, New Taipei Blvd., Xinzhuang Dist. New Taipei City 242032, Taiwan, R.O.C. Tel: +886-2-8919-1230

Tel: +886-2-8919-1230 Fax: +886-2-8522-8623 www.moxa.com

Which products can apply Moxa Industrial Linux v3.4.1?

Product Name	Current OS Image	New OS Image
	(MIL 3.4.0)	(MIL 3.4.1)
UC-1200A Series	v1.3	v1.4
UC-2200A Series	v1.3	v1.4
UC-3400A Series	v1.1	v1.2
UC-4400A Series	v1.2	v1.3
UC-8200 Series	v1.4	v1.5
*If MIL3 is selected via CTO		

When will the new versions be available?

- 1. The MIL 3.4.1 images are available for download on the Moxa product website now.
- 2. UC units scheduled to ship after **November 10** are expected to have MIL 3.4.1 preloaded.

If you have any questions, please contact George Hsiao (<u>georgey.hsiao@moxa.com</u>), or contact your regional sales representative.

Form number: HQ-PD.232 Version: 1.8 Page 3/3